

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-014336**Date Inspected:** 22-May-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1600**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name:	N/A	CWI Present:	Yes	No			
Inspected CWI report:	Yes	No	N/A	Rod Oven in Use:	Yes	No	N/A
Electrode to specification:	Yes	No	N/A	Weld Procedures Followed:	Yes	No	N/A
Qualified Welders:	Yes	No	N/A	Verified Joint Fit-up:	Yes	No	N/A
Approved Drawings:	Yes	No	N/A	Approved WPS:	Yes	No	N/A
				Delayed / Cancelled:	Yes	No	N/A
Bridge No:	34-0006	Component:	OBG				

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance Inspector (QA) Shrikant Utekar was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

TRIAL ASSEMBLY YARD

ULTRASONIC INSPECTION

OBG SEGMENT 8AW

ABF Report No: UT-8W-020

This QA Inspector performed verification Ultrasonic Testing (UT) in accordance with ABF/CT Pattern "D" UT Procedure 001 Revision 1. All recordable Indications if found were recorded on a data sheet that Caltrans QA generates after performing a joint inspection. The members are identified as the weld between side panel and bottom panel (counter weight side) of OBG segment 8AW. The weld designations are as follows.

SEG043A-044 (8AW-S.P to B.P, Counter weight side)

ULTRASONIC INSPECTION

OBG SEGMENT 8AW

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

ABF Report No: UT-8W-021

This QA Inspector performed verification Ultrasonic Testing (UT) in accordance with ABF/CT Pattern "D" UT Procedure 001 Revision 1. All recordable Indications if found were recorded on a data sheet that Caltrans QA generates after performing a joint inspection. The members are identified as the weld between side panel and bottom panel (Cross beam side) of OBG segment 8AW. The weld designations are as follows.

SEG043A-045 (8AW-S.P to B.P, Cross beam side)

ULTRASONIC INSPECTION

OBG SEGMENT 7EW

ABF Report No: UT-7W-079

This QA Inspector performed verification Ultrasonic Testing (UT) in accordance with ABF/CT Pattern "D" UT Procedure 001 Revision 1. All recordable Indications if found were recorded on a data sheet that Caltrans QA generates after performing a joint inspection. The members are identified as the weld between Bottom panel and side panel (Counter weight side) of OBG segment 7EW. The weld designations are as follows.

SEG041A-004 (7EW-S.P to B.P, Counter weight side)

ULTRASONIC INSPECTION

OBG SEGMENT 8BE-8CE

ABF Request No: 05202010-2

This QA Inspector performed verification Ultrasonic Testing (UT) in accordance with ABF/CT Pattern "D" UT Procedure 001 Revision 1. All recordable Indications if found were recorded on a data sheet that Caltrans QA generates after performing a joint inspection. The members are identified as the bottom panel splice weld between OBG segment 8BE and 8CE. Inspection was carried out on repair areas. The weld designations are as follows.

OBE8C-003 (8BE-8CE, B.P)

ULTRASONIC INSPECTION

OBG SEGMENT 8BE-8CE

ABF Request No: 05202010-2

This QA Inspector performed verification Ultrasonic Testing (UT) in accordance with ABF/CT Pattern "D" UT Procedure 001 Revision 1. All recordable Indications if found were recorded on a data sheet that Caltrans QA generates after performing a joint inspection. The members are identified as the side panel splice weld between OBG segment 8BE and 8CE (Bike path side). Inspection was carried out on repair areas. The weld designations are as follows.

OBE8C-004, 005 (8BE-8CE, B.P)

ULTRASONIC INSPECTION

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

OBG SEGMENT 8CE

ABF Request No: 05202010-2

This QA Inspector performed verification Ultrasonic Testing (UT) in accordance with ABF/CT Pattern "D" UT Procedure 001 Revision 1. All recordable Indications if found were recorded on a data sheet that Caltrans QA generates after performing a joint inspection. The members are identified as the weld between edge panel and deck panel of OBG segment 8CE (Bike path side). Inspection was carried out on repair areas. The weld designations are as follows.

CA054-004 (8CE-D.P to EP, B.P side)

Unless otherwise noted, all work observed on this dated appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, +(86) 1500 042 2372, who represents the Office of Structural Materials for your project.

Inspected By:	Utekar,Shrikant
----------------------	-----------------

Quality Assurance Inspector

Reviewed By:	Dawson,Paul
---------------------	-------------

QA Reviewer
